




## LCE O2 Sensor Extension Kit Part #1065035

This kit is designed for the Pre 1988 Toyota exhaust manifolds that had the oxygen sensor located in one of the runners of the exhaust manifold. California CARB requires that the oxygen sensor gets an exhaust sample from all cylinders. Therefore LCE's places the oxygen sensor behind the collector of the header in the connector pipe. LCE recommends to upgrade to the 4 wire oxygen sensor as an upgrade to the single wire. This upgrade is to get the best possible signal from the oxygen sensor to the factory computer for trouble free performance.



## LCE O2 Sensor Extension Kit Part #1065035

This kit is designed for the Pre 1988 Toyota exhaust manifolds that had the oxygen sensor located in one of the runners of the exhaust manifold. California CARB requires that the oxygen sensor gets an exhaust sample from all cylinders. Therefore LCE's places the oxygen sensor behind the collector of the header in the connector pipe. LCE recommends to upgrade to the 4 wire oxygen sensor as an upgrade to the single wire. This upgrade is to get the best possible signal from the oxygen sensor to the factory computer for trouble free performance.

